


Concentricity, Coolant supply

Concentricity



▶ To achieve the tolerance required or eliminate trouble, total run out between the center line of tool and workpiece must not exceed the below value.



External coolant supply



Internal Coolant supply



Coolant Pressure(psi) for YTDI drill

	12mm	25mm	38mm	50mm
3xD	33	29	27	25
5xD	54	45	39	35
7xD	75	70	64	59

Coolant Volume(gpm) for YTDI drill

	12mm	25mm	38mm	50mm
3xD	3	4	5	6
5xD	4	6	8	9
7xD	5	7	9	11

Speed formula, Drilling of stacked plate, Chip formation

Major Cutting speed formula

Cutting Speed

$$V = \frac{\pi D \times N}{1000} \text{ (m/min)}$$


- V : Cutting speed (m/min)
- D : Drill diameter (mm)
- N : Revolution per minute (rpm)
- π : Circular constant (3.14)

Feed


$$f = \frac{F}{N} \text{ (mm/rev)}$$

- f : Feed rate (mm/rev)
- F : Depth of cut per minute (mm/min)
- N : Revolution per minute (rpm)

Recommended application for stacked plate by Yes Carbide Drills




One operation is possible subject to closely tightend stacked plate without any room.



"Woodpecker" method recommended in case of certain aperture in the stacked plate.


Good chip formation




(initial drilling)



(drilling through)





(bottoming)







(long Stringy chip)

Speed Examples, Maximum Wear

Cutting speed examples for different workpieces by Yes Carbide drills


 <p>Φ13 x depth 10mm</p>	<p>FCD45 YCD 130 N=1592rpm V=65m/min F=318mm/min f=0.2mm/rev</p>	 <p>Φ20 x depth 70mm</p>	<p>S50C YTDI 200 P N=876rpm V=55m/min F=263mm/min f=0.3mm/rev</p>
---	---	--	--

 <p>Φ24 x depth 63mm</p>	<p>SS41 YTDI 240 T N=796rpm V=60m/min F=239mm/min f=0.3mm/rev</p>	 <p>Φ12 x depth 12mm</p>	<p>SCM440 YSD 120 N=1194rpm V=45m/min F=179mm/min f=0.15mm/rev</p>
---	--	--	---

 <p>Φ10 x depth 15mm</p>	<p>SUS304 YSDC 100 N=1115rpm V=35m/min F=112mm/min f=0.1mm/rev</p>	 <p>Φ15 x depth 8mm</p>	<p>FC25 YTD 150 N=1592rpm V=75m/min F=557mm/min f=0.35mm/rev</p>
---	---	---	---

How to find maximum wear

1. When long and stringy chip formation without broken chip, require to change new tool or regrinding
2. Below pictures show the time of regrinding



Need to change new tool or regrinding



Excessive wear

Power requirement for YES Carbide Drill

Power requirement for YES Carbide Drills

$$\text{Power}(P) = \frac{D \times f \times V \times ks}{24,480 \times 0.7} \text{ (kw)}$$

ex)

$$\text{Power}(P) = \frac{11.5 \times 0.2 \times 60 \times 230}{24,480 \times 0.7} = 1.852 \text{kw}$$

- D = drill diameter (mm)
- f = feed (mm/rev)
- V = cutting speed (mm/min)
- ks = specific cutting force (kg/mm)
- ? = constants of performance(0.7~0.85)

• Specific cutting force (ks)

	Material	Condition	HB	ks(kg/mm)
Steel	Unalloyed steel	C = 0.15%	100~150	195
		C = 0.35%	120~180	215
		C = 0.60%	200~250	230
	Low alloy steel	Non hardened	120~200	215
		Hardened & Tempered	250~300	265
		Hardened & Tempered	300~350	290
	High alloy steel	Annealed	150~250	265
		Hardened	300~350	290
	Stainless steel	Martensitic/ ferritic	175~225	235
		Austenitic	150~200	250
	Steel casting	Unalloyed	150~200	205
		Low alloyed	175~225	255
High alloyed		200~250	275	
Hard steel	Hardened steel	HRc 55	460	
Cast iron	Grey casting iron	Low tensile strength	150~225	110
		High tensile strength	200~300	150
	Malleable cast iron		110~250	115
	Nodular cast iron	Ferritic	125~200	115
		Pearlitic	200~300	185
Chilled cast iron		350~450	310	
Non ferrous	Aluminium alloys	Non heat treatable	40~80	50
		Heat treatable	80~120	80
	Aluminium alloys,Cast	Non heat treatable	50~100	80
		Heat treatable	65~115	95
	Copper alloys	Brass	65~115	80
		Bronze	75~115	180

Trouble Shooting Guide for YES Carbide Drill

Problem		Cause	Remedy
Cutting edge wear	Flank wear	Excessive cutting speed	Reduce cutting speed
		Vibration or chattering in machine tool, holder or component	Check and adjust machine and tool alignment
	Edge chipping	Deflection of tool, part, fixture or machine	Check all rigidity
		Excessive cutting speed	Reduce cutting speed
		Off center set up	Check concentricity not to exceed 0.02mm TIR
	Corner chipping	Excessive cutting speed	Reduce cutting speed
		Insufficient coolant supply	Increase coolant pressure
	Built up edge	Insufficient cutting speed	Increase cutting speed
		Insufficient coolant supply	Increase coolant pressure
		Worn cutting edge	Regrind or replace new drill
	Margin	Improper seating of tool	Check and adjust machine spindle, and fixture
		Rough or angled entry/exit of hole	Reduce feed
		Chip clogging or jamming	Increase coolant pressure and adjust feed to optimize chip-formation
		Insufficient coolant supply	Increase coolant pressure
		Excessive cutting speed	Reduce cutting speed
Long stringy chips		Improper speed and feed	Adjust speed and feed
Tool life too short		Flank wear increase too fast	Reduce cutting speed
Drill breakage		Off center set up	Check set up rigidity of machine, tool, and fixture
		Improper cutting condition	Check cutting parameters, possibly reduce feed
Burr on exit		Excessive axial force	Reduce the width of edge preparation
Oversize hole		Improper cutting condition	Check cutting data, increase cutting speed
		Clamping chuck	Check fit and clamping of tool
Undersize hole		Tool cooling	Check coolant fluid
		Improper cutting condition	Reduce cutting speed, increase feed


Resharpener Guide for YES Carbide Drills

Yes brand Carbide drill can be resharpened by CNC 5 axis machine or Universal tool grinder with our own special attachment. The below procedure is to regrind by Universal tool grinder, while follow "S" point program in case of CNC machine.


Removal of worn section

Remove all of the worn or chipped section before regrinding.

Regrinding drill point




(1.1)




(1.2)

1. Put the drill point horizontally on the stopper.(see 1.1)
2. Set dial gauge on <a> and turn the drill to coincide central line of point. Then, tighten the collect chuck securely.(see 1.2)




(1.3)



(1.4)


3. Set the cutting edge toward grinding wheel to the point angle <c1, 8°> as shown (1.3). Then, keep the angle <c2, 20°> as shown (1.4).
4. Grind the flank up and down repeatedly as shown <b1>.



(1.5)


5. Move forward the grinding wheel and grind the cutting lips, after keeping the attachment horizontally.
6. Rotate the attachment at 180° toward <c3> and grind other cutting edge by the same procedure as NO.4, 5.(see 1.5) Make sure that both cutting lips should be equal or symmetrical.

Web thinning




(2.1)


1. Set the drill at 30° or 35° in the drill attachment.(see 2.1) (In case of drill for AL, FC material, keep 30°, while others at 35°.)
2. Align the "B" face of wheel at center line of drill.(see 2.2)
3. Set the "B" face of wheel at 45° from central line of the drill.




(2.2)



Cut 1




Cut 2



Cut 3

4. Grind as procedure <cut 1>,<cut 2>, <cut3>.(see 2.3)
5. Rotate the attachment at 180° and grind other facet by NO.4 procedure. Note that the shape of the thinning should be such that it does not interfere with chip flow.



Note

If you have any difficulty to regrind in your shop, you may use our factory expert service which is being serviced at reasonable cost in one week returning delivery Contact ours.